



**BRACEWELL ENGINEERING, INC.**

155 Mast Street, Unit 114, Morgan Hill, CA 95037

(669) 258-5820 FAX (408) 498-7045

www.bracewellengineering.com

September 26, 2018

Michaele LaForge  
City Manager  
City of San Juan Bautista  
P.O. Box 1420  
San Juan Bautista, CA 95045

Re: San Juan Bautista Water System  
Operations and Maintenance Report for August 2018

Dear Ms. LaForge:

The following is our final monthly report for operation and maintenance of the Water System.

**DDW Reporting**

The monthly report to the Division of Drinking Water (DDW) for the San Juan Bautista Water System was submitted by email with a copy sent for the Water System's files. **All monthly routine distribution system bacteriological samples were negative for total coliforms and E. coli.**

The annual distribution system TTHM and halo acetic acids monitoring was completed and the results were below their respective MCLs.

**Water System Operations and Maintenance Status**

**Operations.** The City pumped an average of approximately 0.096 MGD from Well 1. There were no significant operational problems reported.

**Maintenance.** There were no significant unplanned maintenance issues.

**Extra Services**

1. As requested we performed extra coliform monitoring after a main water line break and repair on Lang Street. The results were submitted to DDW staff.

If you require any further information, please do not hesitate to contact me.

Respectfully submitted,  
BRACEWELL ENGINEERING, INC.

Lloyd W. Bracewell, PhD, RCE  
Principal Engineer

cc: BEI Office